Inspection Report for Flood Damage Work

Date:-
1 Name of PIUs: - Gyan vibhalcor
2 Name of Block/Road: - Auri / Param jestar Debbalous D. H. al
Date:- 1 Name of PIUs:- Cryan vibbalear 2 Name of Block/Road:- Awri / Paramjeevar Bhothopur Path Abambur A (A) For Road: 1. Damage Location/Chainage:- many places
1. Damage Location/Chainage :- many places 2. Damage Length :- 0.14323 km 3. Nature of Damage :- 4. Details of Restoration Works :- (i) Material being used in Restoration works:- Brick bats (ii) Equipment's/Tools being used in Restoration works:- Tractor. (iii) Procedure taken up in Restoration works: (iv) Restored Length :- 0.14323 km
(B) For Bridge:
 Damage Location/Chainage :- Damage Length :- Nature of Damage :- Details of Restoration Works :- Material being used in Restoration works:-
(ii) Equipment's/Tools being used in Restoration works:-
(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-
(iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रनंडल,मुजफरसुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

Paramjeevar Bhadopur Path Aadampur Awal to Dih Tola

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

SI. No.	DESCRIPTION	1.200 Km
1		AMOUNT (LAKHS)
2	Jhama metal	0.000
3	Sand Filling	4.647
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	0.000
OTAL C	COST OF PROJECT IN LACS =	4.647

JΕ

RWD

RWD

4.647

RWD

Technically approved for RS 4.647 lac
(Rupees four lac sixty four thousand seven
hundred only)

अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल, मुजफ्फरपुर