

## Inspection Report for Flood Damage Work

Date:-

1 Name of PHUs :- (Nyan Vithalgar)

2 Name of Block/Road :- Purvi Bahiya Panchayat road to Laxmi talu (Gaighat)

(A) For Road: ✓

1. Damage Location/Chainage :- At many point.
2. Damage Length :- 0.0365 km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- brick badd.
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.0365 km

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

18/12/20

Signature of JE/AE/EE

18.12.20

Signature

(Name of Inspection)

EE

RWD WORKS DIVISION

Muzaffarpur East-1

### GENERAL ABSTRACT

Name of Road Purvi Dahiya PMGSY Road to Laxmi Tola

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km) 2.320 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.006
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	4.006
TOTAL COST OF PROJECT IN LACS =		4.006

*GR*  
01/12/2020  
JE  
RWD

*2.320*  
01/12/2020  
AE  
RWD

*g*  
01/12/2020  
EE  
RWD

Technically approved for Rs. 4.01 lacs (Rs. four  
lacs one thousand) only

*1*  
SE, (RWD)  
Wones Circle  
Muzaffarpur