## **Inspection Report for Flood Damage Work**

Date:-
1 Name of PIUs: - Gyan Vi bhakar
2 Name of Block/Road: - Aurai / Repair of roal from Bhairwa Asthan -
2 Name of Block/Road: - Awai   Rebair of roal from Bhairwa Asthan (A) For Road: Panabur Chaule.
1. Damage Location/Chainage :- wary Maces? 2. Damage Length :- 0.5811 lcm 3. Nature of Damage :- 4. Details of Restoration Works :- (i) Material being used in Restoration works:- Brick both (ii) Equipment's/Tools being used in Restoration works:- Tractor.

:- 0-584 Km

## (B) For Bridge:

(iv)

1. Damage Location/Chainage

Restored Length

- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:-(i)
- (ii) Equipment's/Tools being used in Restoration works:-

Procedure taken up in Restoration works:

- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

## **GENERAL ABSTRACT**

Name of Road

Repair of Road From Bhairwa Asthan to Panapur Chauk

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

4.300 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	9.004
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	9.004
OTAL C	OST OF PROJECT IN LACS =	9.004

1111/21

JE

RWD

ARI MOILA

ΔF

RWD

EE TIT

RWD

Technically approved for RS 9.004 lac (Rupees Nome loc four hundred only)

> अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्करपुर