Inspection Report for Flood Damage Work

Date:

- 1. Name of PIUs Gyan vibrakarb
- 2. Name of Block/Road Aurai / Rumber PWD Road to sambhedon
- A. Fer Road
- 1. Damage Location/Chainage : many blaces.
- 2. Damage Length

: 6.05181 Km

- 3. Nature of Damage
- 4. Details of Restoration Works
 - i. Material being used in Restoration works:

Brick bull

ii. Equipments/Tools being used in Restoration works:

Tractor

- iii. Procedure taken up in Restoration works:
- iv. Restored Length

: 0-05/8/1cm

- B. For Bridge
- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - i. Material being used in Restoration works:
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

Signature of JE/AE/EE

Light ure

(Name of Inspector)

GENERAL ABSTRACT

Name of Road

Rampur PWD Road to Shambhuta

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

0.000 Km

SI. No.	DESCRIPTION		AMOUNT (LAKHS)
- 1	Earthwork		0.00
2	Jhama metal	Maria Company	5.97
3	Sand Filling		0.00
4	Sand bag		0.000
5	H.P.		0.000
	GRAND SUB TOTAL		5.973
TOTAL	COST OF PROJECT IN LAC	S =	5.973

RWD

Technically approved for RS 5.973 lac.

(Rupees five lac ninety seven thousand three hundred only)

अधीक्षण अभियंता ग्रामीण कार्य विभाग

कार्य अंचल,मुजफ्फरपुर