## Inspection Report for Flood Damage Work

	- 4	
1 )	216	•_
v	an	

1 Name of PIUs: - Gyan Vibralcon

2 Name of Block/Road: - Awrei / Sahila Balli mmasy to Kothia

:- many places' :- 0.1386 Km 1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage 4. Details of Restoration Works:

(i) Material being used in Restoration works:- Brick bots

Equipment's/Tools being used in Restoration works: - Tractor. (ii)

(iii) Procedure taken up in Restoration works:

(iv) Restored Length :- 6.1386 Km

## (B) For Bridge:

- Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

## **GENERAL ABSTRACT**

Name of Road

Sahila Balli MMGSY to Kothia

**District** 

Muzaffarpur

**Block** 

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

1,500 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	8.117
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	8.117
TOTAL COST OF PROJECT IN LACS =		8.117

11/0

JE

RWD

Alloll

ΑE

RWD

EE

**RWD** 

Technically approved for RS 8.117 lac (Rupeel Eight lac Gleven thousand seven hundred only)

> अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर