Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - Gyan Vibhalcon

2 Name of Block/Road: - Awai | Loys - Tob to Atroha

- 1. Damage Location/Chainage :- many places .
- 2. Damage Length :- 0.047KM
- 3. Nature of Damage
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:- Brick bats (ii)
- Equipment's/Tools being used in Restoration works:-Tractor (iii)
- Procedure taken up in Restoration works:
- (iv) Restored Length :- 0.047 km

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:-(i)
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

L045-T06 to Atraha

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

1.312 Km

SI, No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	0.88
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	0.684
TOTAL C	OST OF PROJECT IN LACS =	0.684

RWD

RWD

Technically approved for Rs 0.684 lac (Rupees sixty Eight thousand four hundred only)

अधीक्षणं अभियंता ग्रामीण कार्य विभाग कार्य अंचल, मुजफ्फरपुर