

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - Aurai / Logo maheshwara to Deora Nali Road


A. For Road

1. Damage Location/Chainage : many places
2. Damage Length : 0.02987 km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Stone beads
 - ii. Equipments/Tools being used in Restoration works: Tractor
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.02987 km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE


25.1.21
Signature

(Name of Inspector)

GENERAL ABSTRACT

Name of Road L080 Maheshwara to Deora Asali Road

District Muzaffarpur

Block Aurai

Division Muzaffarpur East-2

Length of Road (in Km) 0.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	3.311
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	3.311
TOTAL COST OF PROJECT IN LACS =		3.311

[Signature]
19/1/21

JE
RWD

[Signature]
19/01/21

AE
RWD

[Signature]
19.1.2021

EE
RWD

Technically approved for RS 3-311 lac
(Rupees Three lac thirty one thousand one hundred only)

[Signature]
अधीक्षक अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर

~~अधीक्षक अभियंता~~
~~ग्रामीण कार्य विभाग~~
~~कार्य अंचल, मुजफ्फरपुर~~