

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Aurai / Mahua Chowk to Balia

(A) For Road:

1. Damage Location/Chainage :- 0.820 km
2. Damage Length :- 0.02943 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor.
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.02943 km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


25.1.21
Signature

(Name of Inspection)

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road Mahua Chowk to Balia

District Muzaffarpur

Block Aurai

Division Muzaffarpur East-2

Length of Road (in Km) 2.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.385
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	1.385
TOTAL COST OF PROJECT IN LACS =		1.385

544
11/11/21
JE
RWD

11/11/21
AE
RWD

9
11/11/21
EE
RWD

Technically approved for 1.385 lac
(Rupees one lac thirty eight thousand five hundred only)

11/11/21
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर