

1

Name to work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement—
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
NAME OF WORK:- Restoration of Road Kurmi Tola To Demari Tola					
Authority:- E. E. R. W. D. Works Division, Dhamdaha					
1- Supply, Fitting and fixing of bamboo		62 mm to 75 mm dia			
	8 x 84	-	672 mtr.		
2- Labour for driving Bamboo Piles					
	25.20 mtr length		21120 mtr.		

3- fitting and fixing Bamboo woven chain chary					
		84 mtr X 1.50 m			
					= 126 mtr
4- Supply and Spreading of Brick Bats					
		CH-2720 mtr			
		R/S- BM X $(\frac{2.70 + 4.75}{2})$ m			
				$\times (\frac{2.0 + 2.10}{2})$	= 61.09 m ²
		R/S- 10.30 m X $(\frac{3.20 + 4.65}{2})$			
				$\times (\frac{1.40 + 1.50}{2})$	= 58.62 m ²
Continuation					= 119.72 m ²

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dhamdaha

2. Name of Block/Road- Kyrmj Tolg to Dumar Tolg

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 30-40 m

3. Nature of Damage : slope damage due to flood

4. Details of Restoration :

i Material being used in Restoration : Brick Bat

ii Equipment/Tools being used in Restoration works: Tractor

iii Procedure taken up in Restoration works : Manual

iv Restored Length : 30-40 m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Praman
29-1-22
Signature of JE/AE/EE

by
27/1/21
AG

23.01.21
EC

Praman
29/1/2021
Signature
(Name of Inspector)