

Name of work— 1
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
NAME OF WORK- Restoration of Road From S.O. 113 To Nashi Tola under F.D.R.					
Authority - E.E.R.W.D WORKS Division, Dhamdaha.					
1 - Supply, fitting and fixing of Bamboo (62 MM to 75 MM) dia					
		$B \times B = 3.0 M \times 3.0 M = 6.64 M^2$			
2 - Labour for driving 62 MM to 75 MM dia					

Bamboo Piles			
25.0 Meter Length = 1107 Meters.			
3 - Providing and laying R.C.C. Pipe N.P. 3			
10.00 x (MM)			
$2 N.P. \times 2.50 M = 5.0 Meters$			
4 - fitting and fixing in Bamboo Woven chaychay			
$B 3.0 M \times 1.50 M = 124.5 M^2$			
5 - Supply and spreading of Snick Batt			
Continuation			

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
C H - 25.20 m + c					
L/S - 12.0 M X $(2.45 + 3.70) M$					
X $(1.80 + 1.20)$					$= 46.17 M^3$
Full width - 8.20 M X $(2.70 + 5.25) M$					
X $(1.50 + 1.60) M$					$= 56.88 M^3$
R/S - 13.80 M X $(2.62 + 3.65) M$					
X $(0.95 + 1.10 + 1.0) M$					
					$= 44.05$
7 M X 1.50 M X 0.40 M = $4.20 M^3$					
R/S 3.40 M X $(2.15 + 2.75) M$					

$$X \frac{(0.60 + 0.55)}{2} = 4.77 M^3$$

$156.02 M^3$

Pyumon
29-11-2020
(A.C.)

Executive Engineer,
Rural Works Department
Works Division Dhamdaha (Pumea)

Continuation

Date: Inspection Report for flood damage work
1. Name of PIUs: Dhamdaha
2. Name of Block/Road: SO 112 To Nashi Tol 9

A. For Road

1. Damage Location/Chainage :
2. Damage Length : 44.40m
3. Nature of Damage : side slope and top of road washout due to flood
4. Details of Restoration :
i Material being used in Restoration : Brick Bat, Hume pipe, Bombo
ii Equipment/Tools being used in Restoration works: Trolley
iii Procedure taken up in Restoration works : Marmay
iv Restored Length : 44.40m

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration :
i Material being used in Restoration :
ii Equipment/Tools being used in Restoration works:
iii Procedure taken up in Restoration works :
iv Restored Length :

11/01/2021
21-01-2021

Signature of JE/AE/EE

21-01-2021

21-01-2021

Signature
(Name of Inspector)