

Name to work—

1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

NAME OF WORK: Restoration
of Road Chandura Mathura
to Batta Mathura.

Authority: E. P. R. W. D.

Works Division, Dharmadula.

1- supply fitting and
fixing of Bamboo

(62 mm to 75 mm)

B x 49.0 = 392 mtr.

2- Labour for driving 62
mm to 75 mm dia

Bamboo Piles

14. 80 mtr length - 653 mtr.

3- fixing Bamboo woven
chauchary.

49.0 mtr x 1.50 m = 73.5 m²

4- supply and spreading
of Brick Bath

L/s- B M x $\frac{(1.58 + 3.08)}{2}$ m

x $\frac{(1.50 + 1.60 + 1.40)}{3}$ m

= 27.96 m²

L/s- 25 m x $\frac{(1.70 + 3.13)}{2}$ m

x $\frac{(1.20 + 1.80 + 1.50)}{3}$ = 86.54 m

Continuation

T-

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
R/s 21M x (1.35 + 2.05) M		2			
x (1.50 + 1.85 + 1.45) M		3			
					= 72.24 M ³
L/s 38.60M x (1.93 + 3.31) M		2			
x (1.60 + 1.40 + 1.60 + 0.90)		4			
					= 139.06 M ³
L/s 16M x (1.55 + 3.82) x		2			
(1.90 + 3.10 + 1.80)		3			= 97.38 M ³

R/s - 38M x (1.80 + 2.92)		2			
x (0.80 + 1.70 + 0.90)		3			= 101.63 M ³
R/s - 41M x (2.23 + 3.63) M		2			
x (1.20 + 1.90 + 1.10)		3			= 168.18 M ³
					T ₂ 693.21 M ³

Pkumar
 20-11-2020
 20/11/20
 AG
 20/11/20

Executive Engineer,

Construction Works Department

Works Division Dhamdaha (Purnea)

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dharmdaha

2. Name of Block/Road- Chandwa Mohan to Babha Musthar

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 187.60 m

3. Nature of Damage : both side slope damage due to Rainwater

4. Details of Restoration :

i Material being used in Restoration : Border Buf

ii Equipment/Tools being used in Restoration works: Tractor

iii Procedure taken up in Restoration works : Manner

iv Restored Length : 187.60 m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Pruman
27-01-2021
Signature of JE/AE/EE

27-01-21
27-01-21
27-01-21

Signature
(Name of Inspector)