

# FIELD INSPECTION REPORT

|                                                                         |                             |
|-------------------------------------------------------------------------|-----------------------------|
| Date of Inspection :                                                    | District: NALANDA           |
| Division : HILSA                                                        | Length (km): 1.9 K.M.       |
| Name of the Road: L032 BHASIMPUR PILICH ROAD TO RUDDA,                  | PACKAGE-BR-24R-294          |
| Scheme/Programme: MAINTENANCE                                           |                             |
| Package No.: BR-24R-294                                                 | Road Id No.:                |
| Status of the Project: <del>Ongoing/Completed</del> Under Maintenance ✓ | Under Maintenance           |
| Work is a case of: New Connectivity/Up gradation/ Maintenance           | <del>New Connectivity</del> |

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | Pavement                                                                                                             |             |
| a)      | Road Junction condition                                                                                              | S/U         |
| b)      | Condition of Surfacing                                                                                               | S/U U       |
| c)      | Riding Quality                                                                                                       | S/U U       |
| d)      | Road Camber                                                                                                          | S/U U       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No Yes  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No Yes  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No NO   |
| 2.      | Cross Drainage                                                                                                       |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U SRI |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U S   |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U S   |
| 3.      | Road Furniture                                                                                                       |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No NO   |
| 4.      | Compliance History                                                                                                   |             |
| a)      | Status of ATR's & any others                                                                                         | PENDING.    |

Overall Rating :

|                                             |       |
|---------------------------------------------|-------|
| Satisfactory (S)                            |       |
| Satisfactory but requires Improvement (SRI) |       |
| Unsatisfactory (U)                          | ' U ' |

NAME: BRAJESH KUMAR  
A.E.R.W.D. WORKS DIVISION  
HILSA

29/01/2021  
(Signature)