Inspection Report for Flood Damage Work

Date

Cryan vibhousad Name of PIUs-1

Keutsa/sivdows PMC154 to Dhaltila siwan prayugwarsi Chawle Name of Block/Road-2

For Road

- many places. Damage Location/Chainage 1
- Damage Length
- 3 Nature of Damage
- 4 **Details of Restoration Works**
 - grue bands, wear sand i Material being used in Restoration Works-
 - Equipments/Tools being used in Restoration Worksii
 - iii Procedure Taken up in Restoration Works-
 - iv Restored Length 0 1082 cm

For Bridge

- Damage Location/Chainage 1
- 2 Damage Length
- 3 Nature of Damage
- 4 Details of Restoration Works
 - i Material being used in Restoration Works-
 - Equipments/Tools being used in Restoration Worksii
 - Procedure Taken up in Restoration Worksiii
 - iv Restored Length

Signature of JE/ AE/ EE

Signature (Name of Inspector) कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

SIVDAS PMGSY to DAHILA SIWAN PARYAGWARI CHAWK

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

5.375 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
. 1	Earthwork	0 000
2	Jhama metal	2.890
3	Sand Filling	0.150
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	3.040
TOTAL	COST OF PROJECT IN LACS =	3.040

JE

RWD

AE 19.1201

RWD

EE

RWD

Technically approved for RS 3.04 lac (Rupees Three lac Four thousand only)

> अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल, मुजफ्फरपुर