

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Reta / RFO sarai to Lakminiya tala hote hue chandel sian tar.

(A) For Road:

1. Damage Location/Chainage :- many places
2. Damage Length :- 0.166 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick ball
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.166 km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

कार्यपालक अभियंता


ग्रामीण विकास विभाग


कार्य प्रभाग, गुजरातपुर पूर्वी-1


GENERAL ABSTRACT

Name of Road REO Sarak to Lakhminiya Tola hote hue Changel Siwan Tak
District Muzaffarpur
Block Katra
Division Muzaffarpur East-2
Length of Road (in Km) 3.398 Km


Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	3.202
3	Sand Filling	0.426
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	3.628
TOTAL COST OF PROJECT IN LACS =		3.628


25/01/21
JE
RWD


25/1/2021
AE
RWD


EE
RWD

Technically approved for RS 3.628 lac
(Rupees Three lac sixty two thousand Eight hundred only)


अधीक्षक अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर