Inspection Report for Flood Damage Work

D	ate
---	-----

1 Name of PIUs- Gyan vibhakar

2 Name of Block/Road- Kentraf ma Kathelhwari Asthan to uphorali.

A

For Road

- 1 Damage Location/Chainage many places.
- 2 Damage Length
- 3 Nature of Damage
- 4 Details of Restoration Works
 - i Material being used in Restoration Works- Local sand, Brice bests.
 - ii Equipments/Tools being used in Restoration Works-
 - iii Procedure Taken up in Restoration Works-
 - iv Restored Length O. 2815
- B. For Bridge
- 1 Damage Location/Chainage
- 2 Damage Length
- 3 Nature of Damage
- 4 Details of Restoration Works
 - i Material being used in Restoration Works-
 - ii Equipments/Tools being used in Restoration Works-
 - iii Procedure Taken up in Restoration Works-
 - iv Restored Length

Signature of JE/ AE/ EE

Signature
(Name of Inspector)
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल,मुजफरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

Maa Katheshwari Asthan to Uphorali Late Nandu Ram House tak

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

2.000 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
Wester	Earthwork	0.000
2	Jhama metal	0.000
3	Sand Filling	3.059
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	3.059
TOTAL COST OF PROJECT IN LACS =		3.059

RWD

RWD

RWD

Technically approved for RS 3.059 lace
(Rupees Three lac five thousand onthe hundred only)

अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल, मुजफ्फरपुर