## **Inspection Report for Flood Damage Work**

Date:
1. Name of PIUS - RWD Horonaut  1. Name of PIUS - RWD Horonaut
2. Name of Block/Road- Lalgan & Rathada Dati Pailway station.
A. For Road Via Kankluyligar) Fuerox Na
1. Name of PIUS - RWD Hornaut  2. Name of Block/Road-Lalgary Rajabad RWD Path to village Gobalbu  2. Name of Block/Road-Lalgary Rajabad RWD Path to village Gobalbu  A. For Road Via Kanheiyagany Padoi Railway Station.  1. Damage Location/Change- Pot Patch Refair whole in many cheinage  2. Damage Length- Pot Patch Refair  3. Nature of Damage- Heavy Rein/ Flood.  4. Details of Restoration Works-
2. Damage Length- Post Podch Repeut
3. Nature of Damage- Heavy Keuh/ Floog.
In octains of mortal and market a
i. Material being used in Ristoration works- 678B  ii. Equipments/Tools being used in Restoration works-JCB, Treather, Fouli Poller, etc.  iii. Procedure taken up in Restoration works-
ii. Equipments/Tools being used in Restoration works-JCB, Treuto, 10001
iii. Procedure taken up in Restoration works-
iii. Procedure taken up in Restoration works- iv. Restored Length-  B. For Bridge

- 1. Damage Location / Chainage-
- 2. Damage Length-
- 3. Nature of Damage-
- 4. Details of Restoration Works
  - i. Material being used in Restoration work-
  - ii. Equipments/Tools being used in Restoration Work-
  - iii. Procedure taken up in Restoration work-
  - iv. Restored Length-

## C. Requirement Of New CD/Bridge

- i. Name of Road-
- ii. Location Chainage-
- iii. Type of CD work/Length required
  - Upload one photograph of damaged portion if available
  - Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode

Signature of JE/AE/EE

NU14 23-01-21 AB

Cea8 4 93/01/2021 AS 25/1/21
Structurive Engineer
R.W.D. (W)
Division Biharsharif (Nalanda)