

## Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - RWD Hornaunt
2. Name of Block/Road- Chero Nagamoussa Road to Hirdan Bigha.

### A. For Road

1. Damage Location /Change- ch-0.370K.m
2. Damage Length- 0.060K.m
3. Nature of Damage- Heavy Rain/Flood
4. Details of Restoration Works-
  - i. Material being used in Rstoration works- Brick Bats and sand Bag
  - ii. Equipments/Tools being used in Restoration works- JCB, Tractor, Trulli, Roller, etc
  - iii. Procedure taken up in Restoration works- Yes
  - iv. Restored Length- 0.060K.m

### B. For Bridge

1. Damage Location /Chainage-
2. Damage Length-
3. Nature of Damage-
4. Details of Restoration Works-
  - i. Material being used in Restoration work-
  - ii. Equipments/Tools being used in Restoration Work-
  - iii. Procedure taken up in Restoration work-
  - iv. Restored Length-

### C. Requirement Of New CD/Bridge

- i. Name of Road-
- ii. Location Chainage-
- iii. Type of CD work/Length required

• Upload one photograph of damaged portion if available

• Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode

Asst  
23/01/2021  
J.E

AE

Signature of JE/AE/EE  
23.01.2021  
EE

NCS  
23-01-21  
AE

Signature  
25/1/21  
Executive Engineer  
R.W.D. (W)  
Division Bihar Sharif (Nalanda)