

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - RWD Hornaunt
2. Name of Block/Road - Motorable of Road from L027-T03 to Banuntar.

A. For Road

1. Damage Location /Change- 0.865K.m, 0.985K.m
2. Damage Length- 0.025K.m
3. Nature of Damage- Heavy Rain/Flood.
4. Details of Restoration Works-

- i. Material being used in Rstoration works- Brick Bats
ii. Equipments/Tools being used in Restoration works- JCB, Tractor, Trulli, Roller, etc.
iii. Procedure taken up in Restoration works- Yes
iv. Restored Length- 0.025K.m


B. For Bridge


1. Damage Location /Chainage-
2. Damage Length-
3. Nature of Damage-
4. Details of Restoration Works-
i. Material being used in Restoration work-
ii. Equipments/Tools being used in Restoration Work-
iii. Procedure taken up in Restoration work-
iv. Restored Length-


C. Requirement Of New CD/Bridge


- i. Name of Road-
ii. Location Chainage-
iii. Type of CD work/Length required

- Upload one photograph of damaged portion if available
- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode


23-01-21
E.E
Signature of JE/AE/EE


23-01-21
AR


23/1/21
Executive Engineer
R.W.D. (W)
Division Biharsharif (Nalanda)


23/01/2021
J.E
AR