

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs -

RWD Harcourt

2. Name of Block/Road-

moderale of Road from sagarpur to Baruntar

A. For Road

1. Damage Location /Change-

0.230km, 0.400km, 0.960km, 1.10km, 1.75km, 1.35km

2. Damage Length-

0.123 km

3. Nature of Damage-

Heavy Rain / Flood

4. Details of Restoration Works-

i. Material being used in Rstoration works-

Brick Bat

ii. Equipments/Tools being used in Restoration works-

JCB, Tractor, Tooli, Roller, etc

iii. Procedure taken up in Restoration works-

yes

iv. Restored Length-

0.123 km

B. For Bridge

1. Damage Location /Chainage-

2. Damage Length-

3. Nature of Damage-

4. Details of Restoration Works-

i. Material being used in Restoration work-

ii. Equipments/Tools being used in Restoration Work-

iii. Procedure taken up in Restoration work-

iv. Restored Length-

C. Requirement Of New CD/Bridge

i. Name of Road-

ii. Location Chainage-

iii. Type of CD work/Length required

• Upload one photograph of damaged portion if available

• Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode

23/01/2021
J.E. AE

Signature of JE/AE/EE
22-01-21
EE

NUS
23-01-21
AR

23/01/21
Executive Engineer
R.W.D. (W)
Division Biharsharif (Nalanda)