Inspection Report for Flood Damage Work

Date:
1. Name of PIUs - RWD Harnaut 2. Name of Block/Road- Hirsdan Bigha to Hirsdan Bigha A. For Road
2. Name of Block/Road- Hirodan By
1. Damage Location / Change- 0. 185 K·m, 0. 195 K·m, 0.210 K·m
2. Damage Length- 0.048 King Co. in 15 Jood
2. Damage Length- 3. Nature of Damage- O. 048 K: M Revin/ Flood HOONY Revin/ Flood
4. Details of Restoration Works-
i. Material being used in Ristoration works- Boi'ck Balls
ii. Equipments/Tools being used in Restoration works-JCB, 700 CO, 100 CC, 100 CC
iii. Procedure taken up in Restoration works-
iii. Procedure taken up in Restoration works- iv. Restored Length- B. For Bridge
1. Damage Location /Chainage-

- 2. Damage Length-
- 3. Nature of Damage-
- 4. Details of Restoration Works
 - i. Material being used in Restoration work-
 - ii. Equipments/Tools being used in Restoration Work-
 - iii. Procedure taken up in Restoration work-
 - iv. Restored Length-

C. Requirement Of New CD/Bridge

- i. Name of Road-
- ii. Location Chainage-
- iii. Type of CD work/Length required
 - Upload one photograph of damaged portion if available
 - Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode

Executive Engineer Signature (W) Division Biharsharif (Nalanda)