Inspection Report for Flood Damage Work

1. Name of PIUS - RWD Harmaut 2. Name of Block/Road - Harmaut Block Ke Barah Poiwan PMG39. A. For Road Chero Blwa to Barah Poiwan PMG39.
1. Name of PIUS - RWD HOR LOCK re Boroak Grown June
2. Name of Block/Road- Harshaut But Burah Poiwan 11/0739.
A. For Road Chero Blue 100 0.860 Km, 1.20 Kr
1 Damage Location (Change- 10, 1751m, 0, 1851)
Z. Daniage Length
3. Nature of Damage- Heavy war I and ago Dog.
3. Nature of Damage- Heavy Fair, Buts & Sand Boy. 4. Details of Restoration Works- Brick Buts & Sand Boy.
i. Material being used in Ristoration works?
i. Material being used in Rstoration works ii. Equipments/Tools being used in Restoration works-JCB, Toology, Colley, CtC.
iii. Procedure taken up in Restoration works-
iv. Restored Length- 0.199 K·M
B. For Bridge
1. Damage Location /Chainage-

- 2. Damage Length-
- 3. Nature of Damage-
- 4. Details of Restoration Works
 - i. Material being used in Restoration work-
 - ii. Equipments/Tools being used in Restoration Work-
 - iii. Procedure taken up in Restoration work-
 - iv. Restored Length-

C. Requirement Of New CD/Bridge

- i. Name of Road-
- ii. Location Chainage-
- iii. Type of CD work/Length required
 - Upload one photograph of damaged portion if available
 - Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode

Signature of JE/AE/EE

Signature Engine

R.W.D. (W)

93/0/ J.E