

## Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - JIBACH PRASAD

2. Name of Block/Road- NH-30A BARHAINA PUL CHATYANA LINK ROAD TO  
ABU MOHAMMADPUR RWD BALWANPAR MORE

### A. For Road

1. Damage Location /Change- 0.780km, 0.876 km, 0.960km, 1.05 km, 1.26 km, 1.31 km

2. Damage Length- 0.1115 km

3. Nature of Damage- Heavy Rain/Flood

4. Details of Restoration Works-

i. Material being used in Restoration works- Brick Bats

ii. Equipments/Tools being used in Restoration works- J.C.C, Tractor, Trulli, Roller, etc

iii. Procedure taken up in Restoration works-

YES

iv. Restored Length- ~~0.1115 km~~ 0.1115 km

### B. For Bridge

1. Damage Location /Chainage-

2. Damage Length-

3. Nature of Damage-

4. Details of Restoration Works-

i. Material being used in Restoration work-

ii. Equipments/Tools being used in Restoration Work-

iii. Procedure taken up in Restoration work-

iv. Restored Length-

### C. Requirement Of New CD/Bridge

i. Name of Road-

ii. Location Chainage-

iii. Type of CD work/Length required

• Upload one photograph of damaged portion if available

• Attach minimum two photograph (during restoration & after restoration) photographs  
should be Geotags and at least one photo be captured in selfie mode

Asst  
23/01/2021  
J.E

A.E

Signature of JE/AE/EE

Asst  
23-01-2021  
E.E

Asst  
23-01-21  
AR

23/1/21  
Signature  
Executive Engineer  
R.W.D. (W)  
Distt. Biharsarif (Nalanda)