## Inspection Report For Flood Damage Work

1 Name of PIUs: Gopalgany - 1	
2 Name of Block/Road: Gopelary / Mani	kpou Kleisetring head (86 NO Dhala) Malali Tola via Rom Nagar
410 89 40 5	27 m, 2740 m to 2765 m
2 Damage Length: 55.65 m	
3 Nature of Damage: Heavy Rain / Floo	, <b>J</b>
4 Details of Restroration Works:	
i. Material being used in Restoration Works:	Brick Bats
ii Equipments / Tools being used in Restoration	Works: ICB, Tractor, Trol, Belcha, Shawal
iii Procedure taken up in Restoration Works:	Yel
iv Restored Length: 55.65 m,	
B For Bridge	
1 Damage Location / Chainage:	
2 Damage Length:	
Nature of Damage:	
Details of Restroration Works:	
Material being used in Restoration Works:	
ii Equipments / Tools being used in Restoration	Works:
iii Procedure taken up in Restoration Works:	
iv Restored Length :	
Nuber 20 m	N88-120
9.3. \\	22/11-47
JE AE	Signature .
	(Name of Inspector)
	Work Division Signal-2