## FIELD INSPECTION REPORT

Nalanda District: Date of Inspection: 22/12/2020 0.700 100 Length (km): Division: Hornaut Name of the Rond: Gosovi mati Kolaba path (Portion Khanda) to Toi loki bigher MAINTENANCE Scheme/Programme: Road Id No .: Package No.: Ongoing/Completed/Under Maintenance Status of the Project: New Conncetivity/Up gradation/ Maintenance Work is a case of: Remarks Parameters to be checked Sl. No. 1. Pavement S/U Road Junction condition n) S/U Condition of Surfacing b) S/U Riding Quality c) S/U Road Camber d) Whether free from defects such as visible cracks, exposed Yes/No NO c) aggregates in case of CC Pavement. Yes/No Contraction Joints provided or not (CC Pavement) Yes 1) Yes/No Compaction of flank/slope & raincuts if any NO g) Cross Drainage 2. .. Condition of head walls in Hume pipe culverts including its painting S/SRI/U a) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U b) S/SRI/U Condition of railings/slab/approach for Bridges c) Road Furniture 3. Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained a) Compliance History 4. Status of ATR's & any others 8)

Overall Rating

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	×
Unsatisfactory (U)	U

(Signature)

NAME: RAVI KUMAR

DESIGNATION: In Engineer

Scanned with CamScanner