		FIELD INSPI	ECTION REPORT	
Date of In	spection: 25	3/12/20	District: Avaria	
Division: Carte de la constante de la constant				DI
Name of th	he Road: He	ouse of Ajo	ay yadov to Karbola	hor
Scheme/P	ragramme:	MAINTENANCE	Road Id No.:	
Package N Status of th		Ongoing/Complet	ed/Under Maintenance	
Work is a	case of:	New Connectivity	/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked			Remarks
1. P	Pavement			
a) R	Road Junction condition			S/U 2
b) (Condition of Surfacing			S/U
	Riding Quality			S/U
	Road Camber			S/U
V	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			VI CS/110
the second second second	Contraction Joints provided or not (CC Pavement)			Yes/No
	Compaction of flank/slope & raincuts if any			Yes/No
	Cross Drainage			
	Condition of head walls in Hume pipe culverts including its painting			8/SRI/U
b) C	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c) C	Condition of railings/słab/approach for Bridges			8/SRI/U
	Road Furniture			
400 244 20	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
	ompliance Hi	AND DESCRIPTION OF THE PERSON NAMED IN		是"是" (1)
-	SER STORES	& any others		
a) St	atus or rece			
Overall Rating :		Satisfactory (S)		'S'
		Satisfactory bu	t requires Improvement (SRI)	
		Unsatisfactory		
			- Q	a Tro
			(Si	gnature)
AME:				
ante,				