FIELD INSPECTION REPORT

Date of Inspection: 22.12. 2020 District: Purnea				
Division: Purnea Length (Km): 0.450				
Name o	f the Road:	chloting sheke	to 10 to 5027	
Scheme	/Programme :	Maintenance		
ackage	No.:		Road ID No. :	
Status of the Project: Ongoing/Completed/Under Maintenance				
Vork is	a case of:	New Connectivity/Up g		
Sl. No		Parameters to l	be Checked	Remarks
1).	Pavement			
a)	Road Junction condition			✓S/U
b)	Condition of Surfacing			₩S/U
c)	Riding Quality			VS/U
d)	Road Camber			₩S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			∠Yes/No
f)	Contraction Joints provided or not (CC Pavement)			✓Yes/No
g)	Compaction of Flank/Slope & Raincuts if any			₩Yes/No
2).	Cross Drainage			
a)	Condition of Head walls in Hume Pipe Culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U
c)	Condition of Railings/Slab/Approach for Bridges			S/SRI/U
	Road Furniture			
	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			LYes/No
	Compliance His	·		
a)	Status of ATR's	& any others		
erall Ra	ating :	Satisfactory (S)		C
		Satisfactory but requires	Improvement (SRI)	S
		Unsatisfactory (U)		
		Status:		

Name: Regular kiner
Degisnation: TE
RWD, Works Division, Purnea.

(Signature) 22./2.2020