

## FIELD INSPECTION REPORT

pmwsy-II

Date of Inspection :	61-01-2021	District:	Bagusari
Division :	Balia	Length (km):	5.880
Name of the Road:	L221 (NH-31) to Rahua Babin Tola (Sodpur)		
Scheme/Programme:	MAINTENANCE		
Package No.:	BROG P2 R-11	Road Id No.:	3201060230005
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Under Progress

Satisfactory (S)	CS
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


  
01.01.21  
(Signature)

Executive Engineer  
RWD Works Division, Balia

NAME:

DESIGNATION: