## FIELD INSPECTION REPORT

| Date of Inspection: 03/01/2020 District: Kishangani |  |                |                                       |           |  |
|---|--|----------------|---------------------------------------|-----------|--|
| Division: MACLOS ON T - 1 Length(km): 0.650         |  |                |                                       |           |  |
| Name of the Road: Navar pur Soshabagi to Losy.      |  |                |                                       |           |  |
| Scheme  |  |                |                                       |           |  |
| Package No.: Road Id No.:                           |  |                |                                       |           |  |
| Status o  | f the Project:   | Ongoing/Compl  | leted /Under Maintenance              |           |  |
| Work is a case of:                                  |  |                | ty/ Up gradation / Maintenance        | Remarks   |  |
| S1. No  | Parameters to be checked,  |                |                                       | S/U       |  |
| 1.  | Pavement   |                |                                       | S/U       |  |
| a)  | Road Junction Condition  |                |                                       | S/U       |  |
| b)  | Condition of Surfacing   |                |                                       | S/U       |  |
| c)  | Riding Quality   |                |                                       | S/U       |  |
| d)  | Road Camper  |                |                                       |           |  |
| e)  |  |                | as visible cracks, exposed aggregates | C1 C5/110 |  |
|   | in case of CC Pavement.  Yes/No  |                |                                       |           |  |
| f)  | Contraction Joints Provided of Hot (CC Pavellient)   |                |                                       |           |  |
| g)  | Compaction of Hark / Shop & Fameurs if any   |                |                                       |           |  |
| 2.  | Cross Drainage  Condition of head walls in Hume nine culverts including its Painting S/SRI/U |                |                                       |           |  |
| a)  | Condition of flead walls in fluttle pipe curve to motors.                                    |                |                                       |           |  |
| b)  | Collation of Apatiment & Wing Walls, size in 10-2  |                |                                       | S/SRI/U   |  |
| c)  | Condition of rainings/ study approach for English  |                |                                       |           |  |
| 3.  | Road Furniture  Whether sign boards/informatory/cautionary Board/km & 200m  Yes/No           |                |                                       | Yes/No    |  |
| a)  |  |                |                                       | 163/100   |  |
|   | stones/Pavement road markings are provided and maintained                                    |                |                                       |           |  |
| 4.  | Compliance History  Status of ATR's & any others   |                |                                       | 7         |  |
| (a)   | Status of ATR  | s & any others |                                       |           |  |

Overall Rating:

| Satisfactory(S)                             | -   |
|---|-----|
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory(U)                           | A   |

(Signature)

AE

NAME: Ranjeet kumar