BUDGED.

## FIELD INSPECTION REPORT

Date of I	nunection:	1-01-21	District: Roktes	
Date of Inspection: 01-01-24  Division: Res Dies di vision, sacron-1			Length (km): 1. 300 84	
	the Road: Bo		To Bakasara	
	Programme:	MAINTENANCE		
Dankaga	No : 10/10	C S 17	Road Id No.:	
Status of	the Project:\	Ongoing/Completed	/Under Maintenance	
	a case of:	New Connectivity/L	Jp gradation/ Maintenance	
SI. No.	No. Parameters to be checked		Remarks	
1.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			/s/U
c)	Riding Quality			/S/U
d)	Road Camber			∕s/U
c)	Whether free from defects such as visible cracks, exposed Yes/No aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting / S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Purnitu	lre .		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
	Compliance P	iistőhy.		192
a)	Status of ATR	's & any others		

Overall Rating

Satisfactory (S)	"8"
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

1000ddsd

(Signature)

NAME: Makesh Poosad Sal

DESIGNATION: 3'E.