## FIELD INSPECTION REPORT

Date of Inspection: 0	1-01-26	District: Porta	
Division: RWD/W division bysorrow		Length (km):	
	emuda more	To Heminda	
	MAINTENANCE	1010 959	
Package No :		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SI. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber	√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No.	
g)	Compaction of flank/slope & raincuts if any	/Yes/No	
1.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts	- S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
	Compliance Printoly.	- V	
8)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	"9"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Makest PorsadSal

DESIGNATION: 3 P