FIELD INSPECTION REPORT

	Da	te o	f Inspection : &	0.12.20	District: East champa	XAL
	Div	risio	11: Paxau		Length (km): 0. 604	
	Nu	Name of the Road: / 050 -/ 030 Ti				antigation of an interestation of the control of the con-
	501	Schemer rogramme: MAINTENANCE PAGES				
	Tackage (Vo.: 6 (7-11)			R-633 Road Id No.: 31708502057		
	Status of the Project:			Ongoing/Completed/Under Maintenance		
	Work is a case of:		a case of:	New Connectivity/Up gradation/ Maintenance		
	SI. No.		. Parameters to be checked		Remarks	
	1.	1. Pavement		The second secon		
	a)		Road Junction condition			SIU
	b)		Condition of Surfacing			\S/U
	(c)	1	Riding Quality			SIU
	d)	_ _	Road Camber			SIU
	c)	c) Whether free from caggregates in case of CC		rom defects such a e of CC Pavement.	ns visible cracks, exposed	Yes/No
1	1)		Contraction Joints	s provided or not (CC	Pavement)	₩Yes/No
	g)	C	ompaction of fla	unk/slope & raincuts if	any	Yes/No
	2.	Cross Drainage				
	ล)	Condition of head walls in Hume pipe culverts including its painting		NS/SRI/U		
b) c)		Condition of Abutment & Wing walls, Slab in RCC culverts				> s/ski/u
		Condition of railings/slab/approach for Bridges				N.S/SRI/U
	3.	Road Furniture				
	a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No
	4.	Compliance History				
a) .	Status of ATR's & any others			N·A·	

Overall Rating

Satisfactory (S)	<i>'S'</i>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: M'Hilesh Krmar Einst DESIGNATION: Junior Engineer, Rhausadano