FIELD INSPECTION REPORT

Date	of Inspection :	03/01/2021	District: Chapto		
Divis	Division: Chapta-1 Length (km): 1.670 km				
		ilkaback P.	ce tezillabad mathiy	•	
	ne/Programme:	MAINTENANCE	Road Id No.:		
	ige No.:	Oncoine/Completes	d/Under Maintenance		
Status of the Project: Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No.		Parameters fo be checked		Remarks	
1.	Pavement			Zer	
a)	Road Junction condition			"S/U	
ь)	Condition of St	.s/U			
c)	Riding Quality	-S/U			
d)	Road Camber	d Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of flank/slope & raincuts if any				
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				
ь)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
;)	Condition of railings/slab/approach for Bridges				
	Road Furniture	國籍 選問			
5	Whether sign boards/informatory/cautionary Board/km & 200m atones/Pavement road markings are provided and maintained			· Yes/No	
G	Compliance History				
St	tatus of ATR's & any others				

Overall Rating

Satisfactory (S)	-	
Satisfactory but requires Improvement (SRI)	SRI	
Unsatisfactory (U)		

Charles of

(Signature)

NAME:

DESIGNATION: