## FIELD INSPECTION REPORT

of Inspection: 04 01 2021 District: Chapter Costs	210
on: Chapter   Length (km): 19230	
The section of the se	
e/Programme: MAINTENANCE	
Koad Id 140	
Some compressed chief triannellance	
	1654150
Parameters to be checked	Remarks
Pavement	
Road Junction condition	S/U
Condition of Surfacing	S/U
Riding Quality	√s/U
Road Camber .	√S/U
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
Contraction Joints provided or not (CC Pavement)	Yes/No
Compaction of flank/slope & raincuts if any	Yes/No
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	S/SPI/U
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture	
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No V
Compliance History	The Popular
Status of ATR's & any others	
	In the Road: Day NH 19 Se Sak Jolg  e Programme: MAINTENANCE  Road Id No.:  of the Project: Ongoing/Completed/Under Maintenance  s a case of: New Connectivity/Up gradation/ Maintenance  Parameters to be checked  Pavement  Road Junction condition  Condition of Surfacing  Riding Quality  Road Camber  Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Contraction Joints provided or not (CC Pavement)  Compaction of flank/slope & raincuts if any  Cross Drainage  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Road Furniture  Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Compliance History

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

04/01/2021

(Signature)

NAME:

**DESIGNATION:** 

Scanned with CamScanner