FIELD INSPECTION REPORT

Data of I	aspection: 91/12/2027 District: Maland	a l
Division		ESSENSION PROPERTY AND ADMINISTRATION OF PROPERTY ADMINISTRATION OF PROPERTY AND ADMINISTRATION OF PROPERTY ADMINISTRATION
	the Road: Bas un tous PM458 road to Bosum	Has Mus
	the Road: Barynton P19454 Toad to Bossia	17402 -1005
Package		
	the Project: Ongoing/Completed/Under Maintenance	
	n case of: New Connectivity/Up gradation/ Maintenance	
	Parameters to be checked	Remarks
Sl. No.	l'arameters to be eneckeu	Action in
1.	Pavement	
n)	Rond Junction condition	S/U
b)	Condition of Surfacing 5	S/U
c)	Riding Quality S	S/U
d)	Road Camber S	S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement) Yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	10
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	· S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
幸4.5%	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	X

(Signature) 12 20 W

NAME: RAVI KUMAR
DESIGNATION: fr. Engtheer

Scanned with CamScanner