

# FIELD INSPECTION REPORT

Date of Inspection : 21/12/20	District: East Champaran
Division : Barauni	Length (km): 1.0
Name of the Road: Jorafa Chauk Chauradaro to Bahadurpur	
Scheme/Programme: MAINTENANCE MMGSY (AIDB)	
Package No.:	Road Id No.: 31708501902
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance	
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	N/A
b)	Condition of Surfacing	N/A
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	'S'
Unsatisfactory (U)	

21/12/20  
(Signature)

NAME: Mitlesh Kumar Singh  
DESIGNATION: Senior Engineer, Chauradaro