

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan Vibhakar

2. Name of Block/Road - Kalsa / Basant to Basant Khangura Buzurg

A. For Road

- ✓
1. Damage Location/Chainage : 0+020 to 0+100, 0+100 to 0+150, 0+150 to 0+200, 0+200 to 0+250, 0+250 to 0+300, 0+300 to 0+350, 0+350 to 0+400
 2. Damage Length : 0.602 Km approx (0.60199 km)
 3. Nature of Damage : Cracks
 4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick ball
 - ii. Equipments/Tools being used in Restoration works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.602 km (0.60199 km)

X B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

Spec
21.11.20
Signature

(Name of Inspector)

EE

RWD work Division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Basant to Basant Khangura Buzurg

District Muzaffarpur


Block Katra

Division Muzaffarpur East-2


Length of Road (in Km) 1.940 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	8.993
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	8.993
TOTAL COST OF PROJECT IN LACS =		8.993

Say 8.99 lac



JE
RWD




AE
RWD



EE
RWD

*Technically approved for Rs 8.99 lac
(Rupees Eight lac ninety nine thousand only)*



SE
RWD work circle
muzaffarpur