Inspection Report for Flood Damage Work

٠.	-				
-1		2	٠	10	ı
н		и	1	c.	
			-	-	,

- 1. Name of PIUs EE, RWD MAHUA
- 2. 'Name of Block/Road Patepur, Awawakarpur Koahi P. A Soni Lal Rai Ke ghar to yadar Tola mushar A. For Road toler Postepur high school talk

1. Damage Location/Chainage : 1020 to 1031

2. Damage Length

: 11.0 mm

: from slood.

3. Nature of Damage

4. Details of Restoration Works :

- Material being used in Restoration works: Bricks bort & Tharma boulders.
- Equipments/Tools being used in Restoration works:
- Procedure taken up in Restoration works:
- iv. Restored Length

B. For Bridge

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - Material being used in Restoration works:
 - Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - Restored Length

JE STJE/AE/EE A

(Name of Inspector)

ग्रामीण कार्च विभाग वर्गर्व प्रमंडल, महाआ