FIELD INSPECTION REPORT

D	ate o	f Inspection: 2		District: East chan	berau	
	visio			Length (km): 1,7 ex		
Na	me	of the Road: し	66-LO28 Lack	mipes to Blakely	•	
Sel	heme	e/l'rogramme;	MAINTENANCE	PMSSY		
1	Package No.: BR-IR- 650			Road Id No.: 3170850 2074		
		of the Project:	Ongoing/Completed/	Under Maintenance		
Wo	rk is	a case of:	New Connectivity/U	p gradation/ Maintenance		
SI	Sl. No.		Parameters to be checked		Remarks	
1.	1. Pavement					
а)		Road Junction condition			SIU	
b)		Condition of Surfacing			~8/U	
c)		Riding Quality			SIU	
d)		Road Camber			-5/U	
c)	Whether free from defects such as visible cracks, expending aggregates in case of CC Pavement.		s visible cracks, expose	Yes/No		
f)	0	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	C	ompaction of flank/slope & raincuts if any			Yes/No	
2.	C	Cross Drainage				
a)	Co	Condition of head walls in Hume pipe culverts including its painting S/SRJ/U				
b)	Condition of Abutment & Winsen H. Cl. L. D.C.				S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U			
3.	Ro	Road Furniture				
)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					
	Con	ipliance History	,			
\ 5	Status of ATR's & any others					

Overall Rating

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: MILILISK Komas Luigh

DESIGNATION: Junior Engineer, Rascul