MNP 4515 FIELD INSPECTION REPORT

(9)		TILLIO II III		
Date of	Inspection: 0	3001-21	District: Roktos	
		vision, laborn-1	Length (km): 0.725	
		alpur Rotmapus	Path Se Gran Pipan Han	ean TO La
	Programme:	MAINTENANCE		
Package			Road Id No.:	
Status of the Project: Ongoing/Completed			/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
SI. No.		Parameters to be checked		Remarks
1.	Pavement			
a)	Road Junction condition			← S/U
b)	Condition of Surfacing			∠ S/U
c)	Riding Quality			~\$/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No.
g)	Compaction of flank/slope & mincuts if any			_Yes/No
2	Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			-S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Roed Burniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			Yes/No
4	Compliane :	iridity		**
a)	Status of ATR	's & any others		Ho

Overall Rating

Satisfactory (S)	"\$"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Mohost Rodad Sol

DESIGNATION: JE