FIELD INSPECTION REPORT

Date of	Inspection: 9+2	-2020	District: Nawada	
Divisio	m: Rasay	Li	Length (km): 0 : 5 11 14	
	of the Road: Lo-	24-PWD	Kamakol road to va	ay MawaTI
	Programme: MA	INTENANCE `		
Packag			Road Id No.: 108027	00264
			/Under Maintenance	
Work I	s a case of: New		p gradation/ Maintenance	The same of the sa
SI No.		Parameters to	be checked	Remarks
1,	Pavement	it said his	estilia et e	Ž.
a)	Road Junction condition			S/U
ь)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			SIU
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
1.	Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance History			
a)	Status of ATR's & any others			NO

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	_

Ayy (Signalute)2-2020

NAME: SHALEN SINITA

DESIGNATION: JE Poh.

Scanned with CamScanner