FIELD INSPECTION REPORT

Date of Inspection: 30-12-2020 District: GAYA						
Divison: Neemchak Bathani; Sub Division - Manbur Length (Km.: 0.210					Km.	
Scher	ne/Programme: GTSNY	MAINTENANCE H	larijan Toli (Kathol bigho Mirganj Road.		re	
Pack	age No.: N/A		Road Id No.: N/A			
Statu	s of the Project: On going.	Ongoing/Completed/Under Maintenance				
Wor	k is a case of: New Commectivity.	New Connectivity/Up	gradation/Maintenance			
SI.		Parameters to be checked	ed		Remarks	
No.	Pavement					
a)	Road Junction condition	-		S	S/U	
b)	Condition of Surfacing			S	S/U	
c)	Riding Quality			S	S/U	
d)	Road Camber			S	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			No	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			yes	Yes/No	
g)	a t co titio a minute if any			No	Yes/No	
2	Cross Drainage	THE RESERVE				
a)	Condition of head walls in Hume pipe culver	rts including its painting		S	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			N/A	S/SRI/U	
c)	a U. C. W Islandan Procesh for Bridges			N/A	S/SRI/U	
3	Road Furniture	1	The state of the s			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and yes/Nemaintained			Yes/No		
4	Compliance History					
a)	Status of ATR's & any others. No AT	R		-		

Overall Rating

Satisfactory (S)	-	
Satisfactory but requires Improvement (SRI)	SRI	
Unsatisfactory (U)	-	

30/12/2020.

A.E. R.W.D. Man