FIELD INSPECTION REPORT

Date of I	nenaction : 2	0/12/2020	District: Ki Shan gary	
			- Lung No Ling Ken	
THE RESERVE	11310	nywalanga I	Kamto19 Road 76 Bi	Ja/ 70/9
	Programme:	MAINTENANCE		
Package			Road Id No.: 81205918	130
Status of the Project: Ongoing/Completed			/Under Maintenance	
Work is a case of:		New Connectivity/U	p gradation/ Maintenance	Remarks
Sl. No.		Parameters to l	se checked	1976 CT
1.	Pavement	and Justin	以	S/U.SXI
a)	Road Junction condition			S/U S/2
	Condition of Surfacing			
b)				_8/U
c)	Riding Quality			<i>81</i> U
d)	Road Camber Whether free from defects such as visible cracks, exposed Yes/No			
e)	Whether free from defects such as visite aggregates in case of CC Pavement.			
0	Lints provided or not (CC Pavement)			
f)	Contraction Joints provided of not (Yes/No Compaction of flank/slope & raincuts if any			
g)	· · · · · · · · · · · · · · · · · · ·			
2	Cross Drainage S/SRI/U			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained			
		The second of th		产产业等.
4.	Compliance History SRI			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:	