FIELD INSPECTION REPORT

				•
Date of	Inspection: 0	3-01-21	District: Rokted	
Division: RwD(U) division, Sosaron-1			Length (km): 0-600	
Name	of the Road: Am	waliga Bhabla	Burketa Road To Hardoy	Barriga
	Programme:	MAINTENANCE	0	
Packag	e No.:		Road Id No .: WORK JU	st sterr
Status	of the Project:	00 0	/Under Maintenance	
Work is a case of:		New Courectivity/Up gradation/ Maintenance		
SI. No.	No. Parameters to be checked		Remarks	
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Fugaliure			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.1	Compliance Fi	SISTEN .		va
a)	Status of ATR's	& any others		
1	A CONTRACTOR OF THE PARTY OF TH	A CONTRACTOR OF THE PARTY OF TH		1

Overall Rating

Satisfactory (S)	3,8 3,
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Makest Porded Sol

DESIGNATION: 3 12.