## FIELD INSPECTION REPORT

STATE OF THE PARTY OF	Inspection: 23-12-20	District: Buxar	
D0708		Length (km): 1.200 KM	
Name o Scheme	Programme:   MAINTENANCE	Karhasi Road to onis	pamalint
Packago		Road Id No.:	
	f the Project:   Ongoing/Complete	ed/Under Maintenance	
The same of the sa	a case of: New Connectivity	'Up gradation/ Maintenance	
Sl. No.	Parameters t	o he checked	Remarks
1.	Pavement		
a)	Road Junction condition		₩57U
b)	Condition of Surfacing		<b>-57U</b>
c)	Riding Quality		₽57U
d)	Road Camber		L8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		J'es/No
g)	Compaction of flank/slope & raincuts if any		WestNo
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informator stones/Pavement road markings at	y/cautionary Board/km & 200m re provided and maintained	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature) 23.62.30

NAME: