

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020	District: Buxar
Division : Dymraon	Length (km):
Name of the Road: Kesath Bhatta Paise Raghunathpur chulahan	
Scheme/Programme: MAINTENANCE	MMGSY (Gen)
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No -

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRJ
Unsatisfactory (U)	

Edge of Surface to be repaired and Flank to be maintained at some place

21/12/2020
J E

21/12/2020
AE

21/12/2020
AE

(Signature)

NAME: