

## Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Cnyan vibhakar
2. Name of Block/Road - Kedra / Basant Bishwatha road to Kori

### A. For Road

1. Damage Location/Chainage : 0.050km, 0.100km, 0.200km, 0.320km, 0.700km, 0.900km
2. Damage Length : 0.177km 0.950km
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works : Bitum
  - ii. Equipments/Tools being used in Restoration works:
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length : 0.177km

### B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works :
  - ii. Equipments/Tools being used in Restoration works:
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length :

Signature of JE/AE/EE

21.12.20  
Signature

(Name of Inspector)

BE

RWD Home Division  
Muzaffarpur East - 1

### GENERAL ABSTRACT

Name of Road Basant Bishwotha Road to Kopi

District Muzaffarpur

Block Katra


Division Muzaffarpur East-2


Length of Road (in Km)


2.112 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	6.097
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	6.097
TOTAL COST OF PROJECT IN LACS =		6.097


say 6.10 lac

  
JE  
RWD

  
AE  
RWD

  
EE  
RWD

Technically approved for Rs 6.10 lac  
(Rupees six lac Ten thousand only)

  
SE

RWD WORK CIRCLE  
muzaffarpur