Inspection Report for Flood Damage Work

Date:

- 1. Name of PIUs Cryan vibhalcers
- 2. Name of Block/Road katery pahraul to khangwa

W. Fer Road

- 1. Damage Location/Chainage: 0. 300 km, 0.300 km, 0.900 km, 0.950 km, 1.00 km, 1.50 km
- 2. Damage Length say o 219 lcm (0.21895 1cm)
- 3. Nature of Damage
- 4. Details of Restoration Works
 - i. Material being used in Restoration works: Brial ball
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length syj-0.2191cm (0.218951cm)
- B. For Bridge
- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - i. Material being used in Restoration works:
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

Signature of JE/AE/EE

Light ture

(Name of Inspector)

ÈG

Euro work-Dington murafempur Gatt-1

GENERAL ABSTRACT

Name of Road

Pahsaul to Khangura

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

1.500 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
. 1	Jhama metal	4.210
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	4.210
TOTAL C	OST OF PROJECT IN LACS =	4.210

say 4.21 lac

RWD

EE

RWD

Technically approved for RS 4.21 lac (Rupees Four lac Threnty one thousand only)

SE RWD WOOK CITCLE

muzaffarpys