

FIELD INSPECTION REPORT

HM454-664

Date of Inspection : 4/01/2021 District: Darbhanga
 Division : Benipur Length (km): 1.250
 Name of the Road: Kamla Nadi to Purinoda Brahmpatti
 Scheme/Programme: MAINTENANCE
 Package No.: MMUSY (W) Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SRI
c)	Condition of railings/slab/approach for Bridges	✓ SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

4/1/2021
 AE
 (Signature)

NAME:

DESIGNATION: