

FIELD INSPECTION REPORT

MM/LSY-UBN

Date of Inspection :	4/1/2021	District:	Darbhanga
Division :	Benipur	Length (km):	1.105
Name of the Road:	Rambahadur the house to Schni tola		
Scheme/Programme:	MAINTENANCE		
Package No.:	mm/LSY (U)	Road Id No.:	
Status of the Project:	Ongoing Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/RI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/RI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/RI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

Be
4/1/2021
(Signature) *Be*

NAME:

DESIGNATION: