

FIELD INSPECTION REPORT

Date of Inspection: 31-12-20	District: Nalanda
Location: H-159	Length (km):
Name of the Road: Ekangar Aungmyi road to Parish via charakot Nalanda	
Category/Programme: MAINTENANCE	mainten
Page No.:	Road Id No.:
Status of the Project: Ongoing/Completed Under Maintenance	Under maintain
Is it a case of: New Connectivity/Up gradation/ Maintenance	mainten

No.	Parameters to be checked	Remarks
	Pavement	
	Road Junction condition	SRI S
	Condition of Surfacing	SRI S
	Riding Quality	SRI S
	Road Camber	SRI S
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
	Contraction joints provided or not (CC Pavement)	Yes/No Yes
	Compaction of flank/slope & raincuts if any	Yes/No NO
	Cross Drainage	
	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U -
	Condition of railings/slab/approach for Bridges	S/SRI/U -
	Road Furniture	
	Whether sign boards/informatory/cautionary Board/4m & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
	Compliance History	
	Status: IATR & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	